

IT-PMC-1100 P2

10/100M Media Converter (SM & MM)

Introduction:

IT-PMC-1100 P2, 10/100M Media Converter, provides a cost effective plug-and-play solution for long-range 10Base-T or 100Base-TX Ethernet extensions and added benefit of 10/100 auto-negotiation, making it the perfect choice when planning future upgrades of 10Base-T networks. IT-PMC-1100 P2 Ethernet Fiber converters are ultra-miniature in size and feature a shielded RJ45 Ethernet jack, SC/ST/FC style fiber-optic connections. Built-in auto-sensing capabilities enable full or half-duplex Ethernet operation with no configuration required!

Packing List:

IT-PMC-1100 P2 is shipped with following items.

1. IT-PMC-1100 P2×1

2. 5VDC power adapter ×1(Media converter/5VDC)

3. User manual ×1

1



Features:

- 1. Accord to IEEE802.1 10Base-T, IEEE802.3u 100Base-TX, IEEE802.3 100Base-FX.
- 2. MDI/MDI-X auto negotiation, 10M/100M auto negotiation.
- 3. Supports full /half duplex, Point-to-point transparent transfer.
- 4. Power External 5VDC input.
- 5. Plug-and-play, easy to installation.
- 6. Can insert to 2U 19", 14 slots Rackmount (power external).


Pinout Configuration:

Power

IT-PMC-1100 P2 adopt the power supply input is 5VDC external.




Ethernet(RJ45), Optical fiber interface



Optical fiber interface:

Optic fiber interface need use in pairs, OUT port is fiber send side, connect another long-range light of interface fiber receive end IN; IN port is fiber receive side, connect long-range same fiber send side:

Optic fibers spent both ends mark the label (the following picture show: A-A, B-B, can also mark another: A1-A2, B1-B2), in order to use.



NOTE: SC, ST or FC, for optic fiber interface, SM is look the same to MM for form. For example, IT-PMC-1100 P2SM/SC, the optic fiber interface (SC) is look the same to IT-PMC-1100 P2MM/SC.


Ethernet interface:

Ethernet (RJ45) interface supports MDI/MDI-X auto negotiation, can use straight-through cable connect PC or server, use across-over connect cable Switch or HUB.

MDI: PIN 1, 2, 3, 6 connects opposite.

MID-X: $1 \rightarrow 3$, $2 \rightarrow 6$, $3 \rightarrow 1$, $6 \rightarrow 2$

MDI/MDI-X 10Base-T/100Base-TX PIN define as follow:




INTELLISYSTEM


PIN	MDI	MDI-X
1	TX+	RX+
2	TX-	RX-
3	RX+	TX+
6	RX-	TX-
4, 5, 7, 8		_

Note: "TX±" Transfer data±, "RX±" Receive data±, "-" None.

MDI:



MDI-X:



Intellisystem Technologies S.r.l.

Via Augusto Murri, 1 – 96100 Siracusa - Phone + 39 (0)931-1756256 / + 39 (0)2-87167549 - Mobile (+ 39) 335 1880035 em@ll: info@intellisystem.it WEB: http://www.intellisystem.it

LED indications:

LED	STATE	INDICATION	
PWR	OFF	Power Off	
(Power)	BRIGHT	Power On	
100	OFF	10M Ethernet	
(10/100M)	BRIGHT	100M Ethernet	
FX	OFF	Fiber Optic Unit is Faulty	
(Fiber Link Port)	BRIGHT	Fiber Optic Unit is Functional	
Link/Act (TX) (TX Port Link/Activity)	OFF	Ethernet is not Connected	
	FLASHING	Transmitting or Receiving Data	
	BRIGHT	Ethernet is Connected	
Link/Act (FX)	OFF	Fiber Links are not Connected	
(FX Por	FLASHING	Transmitting or Receiving Data	
Link/Activity)	BRIGHT	Fiber Links are Connected	
FDX (Full Duplex/Collision)	OFF	Half-Duplex Mode or Network	
		Disconnected	
		Data Collision Detected	
	BRIGHT	Full-Duplex Mode	

Specifications:

Standards: comply with IEEE802.1 10Base-T, IEEE802.3u

100Base-TX, IEEE802.3 100Base-FX

RJ45 port rate: 10/100Mbps auto negotiation

Optic port rate: 100Mbps

Transfer distance: RJ45port: 100m

Fiber optic: 20, 40, 60, 80, 120km(SM),



2, 5 km (MM) optional RJ45 port cable: UTP 5E

Fiber connector: 2×SC, 2×ST, 2×FC optional

Fiber optic cables: Single Mode:8.3/125,8.7/125,9/125 or 10/125

Muti-Mode:50/125,62.5/125 um

Wavelength: 850nm, 1310nm, 1550nm

Power supply: External 5VDC input

Dimensions: 94.0mm×71.0mm×26.0mm

Installation: support DIN-Rail installation

Operating temp:-10°C to 65°C


Storage temperature: -20 to 70°C

Operating humidity: 5% to 95 %(no condensation)

Warranty: 5 years

Approvals: FCC, CE, RoHS approvals

Applications:



Extending 10/100M Ethernet data distance


Intelliøystem Technologies S.r.l. ia Augusto Murri, 1 – 96100 Siracusa – Phone + 39 (0)931-1756256 / +39 (0)2-67167540 - Mobile (+39) 335 1880035 em @i : info@intelliøystem. IK VEB: http://www.intelliøystem.t



Installation:

IT-PMC-1100 P2 provides DIN-rail and wall mounting two types of installation.


Wall mounting installation



Via Augusto Murri, 1 - 96100 Siracusa - Phone +39 (0)931-1756256 / +39 (0)2-87167549 - Mobile (+39) 335 1880035 em@il: info@intellisystem.it WEB: http://www.intellisystem.it



DIN-Rail Installation



Troubleshooting instructions:

- 1. Make sure the power is connected and turned on.
- 2. Make sure the converter Ethernet and fiber optic cables are connected properly.
- 3. Check the connections according to the connection diagram.
- 4. Check the LED Indication status and identify possible problems from the Indication LED table above.

Note:

- 1. Media Converter is a sensitive electronic item, please do handle with extra care on delivery, shifting and humidity.
- 2. This unit will be warranty for 5 years.
- 3. Whenever there is a problem regarding the quality issue within the warranty period, we will take the responsibility to repair with free.
- 4. After the warranty period, we will charge accordingly depending on the fault or damage.
- 5. Whenever there is a fault, you can contact our technical support after you identify the problem and the alarm.

Common Problems:

1. PWR power supply indicator lamp not lighting

Cause:

- 1. Power supply not properly connected.
- 2. Protector tube damaged.
- 3. Power input tie-line in reverse connection.
- 4. Internal power supply circuit with failure.

Solution:

- 1. Check power switch and jack.
- 2. Replace protector tube.
- 3. Correct power supply line connection.
- 4. Returned to the manufacturer for repair.

2. FX Port Link/Act indicator lamp not lighting Cause:

Optic fiber port link is fault.

Solution:

- 1. Check fiber optic is link or not.
- 2. Check fiber optic loss is high.
- 3. Clean the connector of optic interface.
- 4. Insert the well connector in place.
- 5. Returned to the manufacturer for repair.

3. TX Port Link/Act indicator lamp not lighting

Cause:

Ethernet port link is fault.

Solution:

- 1. Check Ethernet (RJ45) line is link or not.
- 2. Check Ethernet (RJ45) port is loose.
- 3. Check the rate of selected media converter.
- 4. Check the rate of Network.
- 5. Returned to the manufacturer for repair.

4. Network packet loss

Solution:

- 1. Check Ethernet rate or full/half duplex is matched or not.
- 2. Ethernet (RJ45) port is loose contact, or optic port is loose contact and soiled.
- 3. Ethernet cable not comply with Ethernet standard.



Certifications:

